NOTE: Effective 10/02/2001 FL requires IR certification for both x-ray and RAM and will accept certification from any approved CE

State	RCP Status	Phone No.	IR Cert.Contact(s)	E-mail	RAM CE	X-Ray CE	Notes
Alabama	AS	(334) 206-5391	David Turberville	dturberville@adph.state.al.us	Yes	Yes	IR cert. rule became effective 5/25/00, AL has given exams since 2002
Alaska	non-AS	(907) 269-7942	Clyde Pearce	cepearce@alaska.net	No	No	NRC certifies AK's RAM IRs; no current plans to require IR certification for x-ray
Arizona	AS	(602) 255-4845	Aubrey Godwin	agodwin@arra.state.az.us	Yes	Yes	
Arkansas	AS	(501) 661-2173	Jared Thompson	jthompsn@mail.doh.state.ar.us	No	No	AR will require RAM IRs to be certified, and will accept certs from any approved certifying entity; no current plans to require IR certification for x-ray
California	AS	(916) 440-7899	Ed Bailey	ebailey@dhs.ca.gov	No	No	CA plans to become a CE for both RAM and x-ray IR in 2005
Colorado	AS	(303) 692-3036	Steve Tarlton	steve.tarlton@state.co.us	No	No	CO will require RAM IRs to be certified, and will accept certs from any approved CE; no current plans to require IR certification for x-ray
Connecticut	non-AS	(860) 424-3029	Edward Wilds	edward.wilds@po.state.ct.us	No	No	NRC certifies CT's RAM IRs; no current plans to require IR certification for x-ray
Delaware	non-AS	(302) 739-3787	Gary Lynn		No	No	NRC certifies DE's RAM IRs; no current plans to require IR certification for x-ray
Dist. of Columbia	non-AS	(202) 535-2180	Harold Monroe	hmonroe@dchealth.com	No	No	NRC certifies DE's RAM IRs; no current plans to require IR certification for x-ray

KEY:	AS = Agreement State	IR = industrial radiography, ind. radiographer	RAM = radioactive material
KE1.	CE = Certifying Entity	non-AS = non-Agreement State	RCP = radiation control program

State	RCP Status	Phone No.	IR Cert.Contact(s)	E-mail	RAM CE	X-Ray CE	Notes
Florida	AS	(850) 245-4545 (904) 359-6363	RAM: Walter Cofer X-ray: Phil Thoma	walter_cofer@doh.state.fl.us philip_thoma@doh.state.fl.us	No	No	FL will require both RAM and x-ray IRs to be certified, and will accept certs from any approved CE
Georgia	AS	(404) 362-2675	Eric Jameson	ejameson@mail.dnr.state.ga.us	Yes	No	GA has no current plans to require certification for x-ray IRs
Hawaii	non-AS	(808) 586-4700	Russell Takata	nriaq@keystroke.net	No	No	NRC certifies HI's RAM IRs; HI plans to become a CE for x-ray IR in 2002
Idaho	non-AS	(208) 334-2235 Ext 245	David Eisentrager	eisentra@idhw.state.id.us	No	No	NRC certifies ID's RAM IRs; no current plans to require IR certification for x-ray
Illinois	AS	(217) 785-6982	Steven Collins	collins@iema.state.il.us	Yes	Yes	IL began IR certification in 1994
Indiana	non-AS	(317) 233-7153	Rex Bowser	rbowser@isdh.state.in.us	No	No	NRC certifies IN's RAM IRs; no current plans to require IR certification for x-ray
Iowa	AS	(515) 725-0301	Ramona Ubaldo-Mealey	rubaldo@idph.state.ia.us	Yes	Yes	
Kansas	AS	(785) 296-1563	Justin Spence	jspence@kdhe.state.ks.us	No	No	KS will require RAM IRs to be certified, and will accept certs from any approved CE; no current plans to require IR certification for x-ray
Kentucky	AS	(502) 564-7818, Ext 3697	Robert L. Johnson	robert1.johnson@ky.gov	No	No	KY will require both RAM and x-ray IRs to be certified, and will accept certs from any approved CE
Louisiana	AS	(225) 219-3027 (225) 219-3041	Tabitha Rice Ann Troxler Brad Schexnayder	tabitha.rice@la.gov ann.troxler@la.gov brad.schexnayer@la.gov	Yes	Yes	
Maine	AS	(207) 287-5696	Shawn Seeley	shawn.seeley@maine.gov	Yes	Yes	

KEY:	AS = Agreement State	IR = industrial radiography, ind. radiographer	RAM = radioactive material
KE1.	CE = Certifying Entity	non-AS = non-Agreement State	RCP = radiation control program

State	RCP Status	Phone No.	IR Cert.Contact(s)	E-mail	RAM CE	X-Ray CE	Notes
Maryland	AS	(410) 631-3300	Ray Manley	rmanley@mde.state.md.us	No	No	MD will require RAM IRs to be certified, and will accept certs from any approved CE; no current plans to require IR certification for x-ray
Massachusetts	AS	(617) 727-6214	Agostino Savastano Ken Traegde	agostino.savastano@state.ma.us kenath.traegde@state.ma.us	No	No	MA will not give exams, but will become a CE by accepting certs from other CEs, and will issue state ID cards for both RAM and x-ray
Michigan	non-AS	(517) 335-8204 (517) 241-1989	RAM: Bob Skowronek X-ray: Jim Camburn	skowronb@state.mi.us jim.camburn@cis.state.mi.us	No	No	NRC certifies MI's RAM IRs; no current plans to require IR certification for x-ray
Minnesota	non-AS	(651) 215-0935	Tim Donakowski	timothy.donakowski@health.state.mn.us	No	No	MN has notified NRC of intent to become an AS, and plans to become a CE for both RAM and x-ray IR, but will not proctor exams; state ID cards will be issued based on IR certs from other CEs
Mississippi	AS	(601) 987-6893	Robert Goff	rgoff@msdh.state.ms.us	No	No	MS will require RAM IRs to be certified, and will accept certs from any approved certifying entity; no current plans to require IR certification for x-ray
Missouri	non-AS	(573) 751-6111	Keith Henke	henkek@dhss.mo.gov	No	No	NRC certifies MO's RAM IRs; no current plans to require IR certification for x-ray
Montana	non-AS	(406) 444-5266	Denzel Davis	ddavis@state.mt.us	No	No	NRC certifies MT's RAM IRs; no current plans to require IR certification for x-ray
Nebraska	AS	(402) 471-0528	Julia Schmitt	julia.schmitt@hhss.state.ne.us	No	No	NE will require RAM IRs to be certified, and will accept certs from any approved CE; no current plans to require IR certification for x-ray

KEY:	AS = Agreement State	IR = industrial radiography, ind. radiographer	RAM = radioactive material
KE1.	CE = Certifying Entity	non-AS = non-Agreement State	RCP = radiation control program

State	RCP Status	Phone No.	IR Cert.Contact(s)	E-mail	RAM CE	X-Ray CE	Notes
Nevada	AS	(775) 687-5394 Ext. 276	Stan Marshall	smarshall@bhps.state.nv.us	No	No	NV requires RAM IRs to be certified; accepts certs from any approved CE; no current plans to require IR certification for x-ray
New Hampshire	AS	(603) 271-4585	Diane Tefft	dtefft@dhhs.state.nh.us	No	No	NH requires RAM IRs to be certified; accepts certs from any approved CE; no current plans to require IR certification for x-ray
New Jersey	non-AS	(609) 984-5636	Jill Lipoti	jlipoti@dep.state.nj.us	No	No	NRC certifies NJ's RAM IRs; no current plans to require IR certification for x-ray
New Mexico	AS	(505) 476-3236	Bill Floyd	william_floyd@nmenv.state.nm.us	No	No	NM will require RAM IRs to be certified, and will accept certs from any approved CE; no current plans to require IR certification for x-ray
New York	AS	(518) 457-1202	Clayton Bradt	dolrhu@nysnet.net	No	No	NY will require RAM IRs to be certified, and will accept certs from any approved CE; no current plans to require IR certification for x-ray
North Carolina	AS	(919) 571-4141	Robin Haden	robin.haden@ncmail.net	No	No	NC will require RAM IRs to be certified, and will accept certs from any approved CE; no current plans to require IR certification for x-ray
North Dakota	AS	(701) 328-5188	Ken Wangler	kwangler@state.nd.us	Yes	Yes	ND offers their exam once or twice a year, depending on the number of requests received
Ohio	AS	(614) 644-2727	Mike Snee	msnee@gw.odh.state.oh.us	No	No	OH requires RAM IRs to be certified; accepts certs from any approved CE; no current plans to require IR certification for x-ray

KEY:	AS = Agreement State	IR = industrial radiography, ind. radiographer	RAM = radioactive material
KE1.	CE = Certifying Entity	non-AS = non-Agreement State	RCP = radiation control program

State	RCP Status	Phone No.	IR Cert.Contact(s)	E-mail	RAM CE	X-Ray CE	Notes
Oklahoma	AS	(405) 702-5141	Pamela Bishop	pamela.bishop@deq.state.ok.us	Yes	No	
Oregon	AS	(503) 731-4014 Ext 669	Terry Lindsey	terry.d.lindsey@state.or.us	No	No	OR will require RAM IRs to be certified, and will accept certs from any approved CE; no current plans to require IR certification for x-ray
Pennsylvania	non-AS	(717) 787-3720	William Kirk	kirk.william@dep.state.pa.us	No	No	PA has notified NRC of intent to become an A.S., but does not plan on becoming a CE; will require RAM IRs to be certified, and will accept certs from any approved CE; no current plans to require IR certification for x-ray
Puerto Rico	non-AS	(787) 274-7816	Osiris Siurano	osiurano@salud.gov.pr	No	No	NRC certifies PR's RAM IRs; no current plans to require IR certification for x-ray
Rhode Island	AS	(401) 222-3434	Bill Dundulis	billd@doh.state.ri.us	No	No	RI will require RAM IRs to be certified, and will accept certs from any approved CE; no current plans to require IR certification for x-ray
South Carolina	AS	(803) 737-7407	James Peterson	petersjk@columb54.dhec.state.sc.us	No	No	SC will require RAM IRs to be certified, but has not finalized its process; no current plans to require IR certification for x-ray
South Dakota	non-AS	(605) 773-6719	Bob McDonald		No	No	NRC certifies SD's RAM IRs; no current plans to require IR certification for x-ray
Tennessee	AS	(615) 532-0383	Johnny Graves	Johnny.Graves@state.tn.us	No	No	TN will require RAM IRs to be certified, and will accept certs from any approved CE; no current plans to require IR certification for x-ray

KEY:	AS = Agreement State	IR = industrial radiography, ind. radiographer	RAM = radioactive material
IXE1.	CE = Certifying Entity	non-AS = non-Agreement State	RCP = radiation control program

IR cer

State	RCP Status	Phone No.	IR Cert.Contact(s)	E-mail	RAM CE	X-Ray CE	Notes
Texas	AS	(512) 834-6688, Ext. 2229	Bridget Stephens	Bridget.Stephens@dshs.state.tx.us			Yes Yes TX developed the first other state RCPs can contract to use it
Utah	AS	(801) 536-4250	Craig Jones	cwjones@utah.gov	No	No	UT requires RAM IRs to be certified; accepts certs from any approved certifying entity; no current plans to require IR certification for x-ray
Vermont	non-AS	(802) 865-7743	Carla White	cwhite@vdh.state.vt.us	No	No	NRC certifies VT's RAM IRs; no current plans to require IR certification for x-ray
Virginia	non-AS	(804) 786-5932	Les Foldesi	lfoldesi@vdh.state.va.us	No	No	NRC certifies VA's RAM IRs; no current plans to require IR certification for x-ray
Washington	AS	(360) 236-3224	Arden Scroggs	arden.scroggs@doh.wa.gov	No	No	WA will require RAM IRs to be certified in 2001, and will accept certs from any approved CE; no current plans to require IR certification for x-ray
West Virginia	non-AS	(304) 558-3526	Beattie DeBord	bdebord@wvdhhr.org	No	No	NRC certifies WV's RAM IRs; no current plans to require IR certification for x-ray
Wisconsin	AS	(608) 267-4784	Mark Bunge	bungemc@dhfs.state.wi.us	No	No	WI has no plans to become a CE, but will require both RAM and x-ray IRs to be certified; will be accepting certs from any approved CE
Wyoming	non-AS	(307) 777-7753	David Finley	dfinle@state.wy.us	No	No	NRC certifies WY's RAM IRs; no current plans to require IR certification for x-ray

KEY:	AS = Agreement State	IR = industrial radiography, ind. radiographer	RAM = radioactive material
	CE = Certifying Entity	non-AS = non-Agreement State	RCP = radiation control program